Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream

Well Operator: Well Name:

Field Name: Well File #:

Date Incident: 10/12/2014 Time Incident: 18:00 Facility ID Number:

County: MCKENZIE Twp: 149 Rng: 100 Sec: 18 Qtr:

Location Description: 2114 134th Avenue NW

Arnegard, ND 58835

Submitted By: Mitch Anderson Received By:

Contact Person: Mitch Anderson

2700 Lincoln Avenue SE Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Yes

Spilled Units Recovered Units Followup Units

Oil Brine

Other 2200 Gallons

Description of Other Released Contaminant:

Methanol, visible pooled quantity has evaporated/volatilized

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards associated with this spill event.

Areal Extent:

No report from the field at this time

Potential Environmental Impacts:

There were no adverse environmental impactes associated with this spill event.

Action Taken or Planned:

Contaminated soil above the action levels will be transported off-site to a licensed landfill.

Wastes Disposal Location: Licensed and approved landfill

Agencies Involved: McKenzie County LEPC Director

Updates

Date: 10/13/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to tank overflow during methanol transfer on facility location. Followup is necessary.

Called company contact at 17:10 this date. Release due to inattention of operator. Majority of the methanol had been recovered or had evaporated. Facility is underlain by clay. Warned the contact that methanol, as it degrades in the soil, can generate explosive amounts of methane. Contact will conduct sampling to ensure contaminant removal from the facility soil.

Date: 10/15/2014 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

10/15/14 at 11:23, on location. Met with report contact. Spill occurred when transferring fluid from large stock tank within secondary containment to the smaller tank outside of containment and adjacent to northwestern corner of compressor engine building. There was dried mud visible around smaller tank but no freestanding liquid visible. Contact dug into dried mud ~1/2 foot and found no freestanding liquid visible there as well. Drainage ditch runs alongside smaller tank (coming from where dried mud is visible) and flows around the compressor building to the south, going through two culverts before opening to the south side of the facility. Since no freestanding liquid remains, the flowpath of methanol was difficult to estimate. Based on dried mud, it does not appear that the methanol reached the first culvert, and so it would not have been able to make it off the facility grounds. Discussed with report contact; company has ordered a PID for the cleanup crew to use when excavating the dried mud around the smaller tank where the overflow occurred. Crew will take measurements as they excavate to make sure the excavation is deep enough. They also will take measurements in front of the first culvert to verify that no methanol flowed into it. Report contact will notify NDDoH of cleanup progress.

Date: 8/20/2015 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

8/27/2015 at 14:53, on location. Excavated area has been filled in. No further followup required.